COMPLETION REPORT

1. Name of Work : **MAINTENANCE OF BOREWELL AT SIDEDAHALLI VILLAGE LIMIT IN BAGALAGUNTE IN WARD NO.14.**

2. Sanctioned Estimate No. & Dt :

3. Head of Account which is Chargeable : P-Col 1221.

4. Work Order No. & Dt :

5. Name of Contractor : **SRI B M YOGANANDA**

6a. Time stipulated for completion of work :

b. Delay in execution of work : --

7. Measurement recorded in : M.B. No. 16801011

8. Check measurement of the Asst. : M.B. No. 16801011 Page No. 1629221 to 1629222

Asst. Exe. Eng. / Exe. Eng : Page No. 1629221 to 1629222

9. Name of the Office / Official :

incharge of the work :

10. a) Asst. Engineer

b) Asst. Exe. Engineer

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
10 Lakhs	9536907	—	463107

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER
W-14

ASST. EXECUTIVE ENGINEER
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
ACCOUNTS SUPTD. (
Bruhat Bangalore Mahanagara Palike.
Dasarahalli Zone, Bangalore-57.